

### 3\_Drilling holes in stainless steel pipe



Drilling tool, drill, machine and special oil for stainless steel

Drilling tool, drill, machine and lube



Use a strong plier to change angle of the drilling tool



Angled drilling tool placed at pipe



Best velocity for drilling is 2600 rpm  
Remember to lubricate drill often